Officials clean up motor oil after spill at fire-damaged auto service





Crews work to contain hundreds of gallons of oil that escaped into a local stream after leaking from plastic oil storage containers that ruptured due to fire at a nearby quick lube.....

Single Wall Oil Tank Double Wall Oil Tank

Steel tanks



Image of an Onken double wall oil tank from a fire in Ferguson, MO Still in tact with no leaks!



PO Box 72
Easton, Illinois 62633
309.562.7271
www.onkens.net